



January 7, 2008

Supplement to SAR Test Report for Motorola portable cellular phone (FCC ID IHDT56JB1)

Prepared by:

Paul Ma

Motorola Mobile Devices Product Safety Laboratory

Libertyville, Illinois

9) Please clarify which RC/SO mode was used during testing for the SAR evaluation. It is not stated in Section 6.1 or 6.2 of Exhibit 11.

The mode is as stated in Section 6.1, CDMA RC3/SO55 mode.

11) Power Supply 6623A and Directional Coupler 778D used in HAC RF Emissions evaluation appears to be out of calibration. Please address.

Updated table below:

Description	Serial Number	Cal Due Date
Power Supply 6623A	US37360826	11/16/2008
Signal Generator E4438C	MY45092912	3/5/2008
Amplifier 1030 BBM3Q7E9I	1040	
3db Attenuator 8491A	50579	3/15/2008
Directional Coupler 778D	18625	9/19/2007
Power Meter E4417A	MY45100481	3/7/2008
Power Sensor #1 - E9323A	MY44420341	12/1/2007
Power Sensor #2 - E9323A	US40412067	3/5/2008
10db attenuator 8491A	3929M50702	3/15/2008
Spectrum Analyzer E4403B	US39440471	3/5/2008

12) Please explain the approximation notation reference in regards to the input power to the dipole validation section on Page 5, Exhibit 6B-1.

Updated tables below:

**Table 4: Dipole Measurement Summary**

Dipole	F (MHz)	Protocol	Input Power (mW)	E-Field Results (V/m)	Target for Dipole (V/m)	% Deviation
SN 1075	835	CW	100	172.6	165.2	4.5
SN 1034	1880	CW	100	135.1	132.5	2.0

Dipole	F (MHz)	Protocol	Input Power (mW)	H-Field Results (A/m)	Target for Dipole (A/m)	% Deviation
SN 1075	835	CW	100	0.481	0.444	8.3
SN 1034	1880	CW	100	0.470	0.453	3.8

13) Please update Page 8 Exhibit 6B-1 with the updated procedure that incorporates method shown in test photographs.

The arch is removed once testing on the unit begins.

14) Please explain conducted setup in Figure 5 Exhibit 7A-1 for RF Emissions testing. The RF Emissions testing is to be performed without RF cable (which would bypass the radiating antenna thereby lowering the emissions). Please clarify.

The RF Emissions testing is performed without the RF cable. See below.



15) Please clarify if RF cable was connected to the EUT during T-coil testing. It is not clear in Figure 6, Exhibit 7A-2.

The RF cable is connected during T-Coil testing. See below.



16) Please address effect of updated procedure on the uncertainty budget on Page 20, Exhibit 6B-1.

The effect of the updated procedure remains unchanged.