



Setup Photos


Revision	Report Date	Reason for Revision
Ø	July 1, 2021	Initial Issue.



Radiated Spurious Emissions, 1GHz – 18GHz, Test Setup




Substitution Method, Test Setup



30MHz – 1GHz, Part15B Test Setup



OTA EIRP Measurement, Test Setup, View 1



OTA EIRP Measurement, Test Setup, View 2