




REPORT NO: 4789232324-1

Page 1 of 5


Appendix I

External Photographs

Top View of EUT




Bottom View of EUT




Front View of EUT




Back View of EUT-1



Back View of EUT-2



Left View of EUT



Right View of EUT



Page 5 of 5

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch
This report shall not be reproduced except in full, without the written approval of UL Verification Services
(Guangzhou) Co., Ltd, Song Shan Lake Branch.