




Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)



Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK19041784



Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)





Equipment Photographs

(Internal)



Equipment Photographs

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK19041784

Equipment Photographs

(Internal)

