



Antenna environment processing



此处接地需用合适泡棉没接好地会影响天线性能


Antenna environment processing



Antenna environment
processing



DRX antenna loading
coil



brief summary

Note: The main antennas original condition test was abnormal, after disassembling it was found that the sponge grounding effect at the screen connection below the main antenna was poor, then it was regrounded and the test was repeated, which was normal. The diversity antenna was optimized to improve sensitivity. The difference in screen brightness is still relatively large at low frequencies, further environmental processing will be done to see if it helps with screen brightness.



Note: These two need to be grounded with a high enough grounding foam, not properly connected will affect the performance of the main antenna