

INTERTEK TESTING SERVICE

Report No:19091333HKG-005

19091333HKG-006


19091333HKG-007

19091333HKG-008

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)



INTERTEK TESTING SERVICE

Report No:19091333HKG-005
19091333HKG-006
19091333HKG-007
19091333HKG-008

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)



INTERTEK TESTING SERVICE

Report No:19091333HKG-005
19091333HKG-006
19091333HKG-007
19091333HKG-008

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)



INTERTEK TESTING SERVICE

Report No:19091333HKG-005

19091333HKG-006

19091333HKG-007

19091333HKG-008

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)



INTERTEK TESTING SERVICE

Report No:19091333HKG-005

19091333HKG-006

19091333HKG-007

19091333HKG-008

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)



INTERTEK TESTING SERVICE

Report No:19091333HKG-005
19091333HKG-006
19091333HKG-007
19091333HKG-008

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)

