

2 Corporate Center Drive
Melville, NY 11747
516-577-2000


ATCB015049 CSF8DL / 573F-5824 CLASS 2 PERMISSIVE CHANGE

Date: 02/18/2014

To Whom It May Concern:

Please be advised that a drawing error has been discovered on the schematic submitted with application ATCB015049. The error is on the schematic for one of the two Honeywell keyfob Models in this application: model TSSCRF115011U. This error is located on sheet 2 of the schematic exhibit (filename, "5834 PC2 EXHIBIT 2-3 SCHEMATIC COMPARISON.pdf"). The 10pF capacitor with refdes 'XC6' should be marked as refdes 'C6' (no 'X'), to indicate that this part is in fact populated. C6 was populated on the assembly used for all tests and measurements in this Permissive Change; the error is in the drawing only. A new drawing is being uploaded along with this cover letter, with the error corrected. Its filename is: "5834 PC2 EXHIBIT 2-3_A SCHEMATIC COMPARISON" ('A' is added).

Regards,

X 
Andrew Roussin