

Response to TCB Findings

1. The label is missing the "ID" after the "FCC". It should read as "FCC ID". Please supply a corrected label sample.

[Revised label drawing supplied.](#)

2. Complete user/instruction manual must be supplied. The copy submitted appears to be first 11 pages of the manual. Please supply the whole manual.

[Complete user's manual supplied.](#)

3. Please note that the band-edge compliance must be shown with regular BW settings used above 1GHz, namely 1MHz RBW and VBW. If this causes significant contribution from the fundamental near the band-edge and cause it to fail, then marker delta method of DA 00-705 can be used to show compliance. Please supply test data showing compliance at the band-edges with 1MHz RBW & VBW.

[Revised test report supplied.](#)