



MOTOROLA

Date: January 10, 2008

Subject: Request for additional information regarding FCC ID: IHDP56HB1

Reference:

Correspondence Reference Number: IHD71084
Confirmation Number: 712311084
Date of Original Email: January 8, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois

Questions and responses follow:

1. E4419B appears to have a past cal due date compared to the test dates. Please clarify.

Response: The calibration date in the original report was a typo, and should read "Jul-19-2008". A corrected report is provided.

2. Please confirm if voice 1 slot operation is the only allowable/applicable configuration using the arm-band accessory or if 1 slot operation represents the worst-case. There appears to be no justification for why multislot operation was not investigated with the arm band.

Response: The following from the user's manual (Exhibit 8a) applies:

Data Operation

When using any data feature of the phone, with or without an accessory cable, position the phone and its antenna at least 1 inch (2.5 centimeters) from your body