



## EMC TEST SETUP PHOTOS



EMC Report #21943 AC Line - Part 15



EMC Report #21943 Part 15, PC Peripheral



EMC Report #21943 Antenna - Substitution



EMC Report #21943 Tx Radiated