



MOTOROLA

Date: April 18, 2008

Subject: Request for additional information regarding FCC ID: IHDT56JF1

Reference:

Correspondence Reference Number: IHD80238
Confirmation Number: 803260238-40
Date of Original Email: April 16, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Confidentiality Letter body text states a different FCC ID than the subject device. Please amend.

Response: Please refer to the revised Exhibit 13 attached.

2. Please confirm if CDMA transmitter can simultaneously transmit with the GSM/GPRS transmitter.

Response: It is confirmed that CDMA transmitter can NOT simultaneously transmit with the GSM/GPRS transmitter. The software has made the GSM transmitter automatically shut down while CDMA transmitter is on.

3. Please include Bluetooth Block Diagram including clock/oscillator values.

Response: Please refer to the revised Exhibit 4 attached, the Bluetooth block diagram with clock/oscillator values is shown on page 2 of the exhibit.

4. Schematics appear to have WLAN circuitry. Please confirm if this will not be available for this application.

Response: It is confirmed that this device is not a WLAN capable device.

5. Conducted Power Plots on page 11 are much less than 0.5 dB lower than the powers stated on Page 6 for GSM1900. Please clarify.

Response: Please refer to the revised EMC report attached where the reference power value for GSM1900 has changed.