



MOTOROLA

Date: October 21, 2005

Subject: Request for additional information regarding FCC ID: IHDT6FJ1 (Portable PCS GSM transceiver)

Reference:

Application Received:	09/28/2005
Correspondence Reference Number:	150928A.IHD
Confirmation Number:	1509280475/ 0476
Date of Original Email:	10/20/2005

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois

Questions and responses follow:

1. Page 42 of the Bluetooth Test Report shows an incorrect plot for "High Bandedge with Hopping Disabled". Please submit the correct plot.

RESPONSE: Please reference Supplemental EMC Report submitted on October 21, 2005.

2. It appears that the 2 power sensors listed on p.4 of the SAR Report may have been past their cal due date for the measurements made on 9/21/05. Please address.

RESPONSE: Please reference Supplemental SAR Report submitted on October 21, 2005.

3. Because of the presence of the Part 15 device (Bluetooth), the User's Manual is required to contain the statement from Section 15.21, which is not present. Please confirm that it will be included in the manual prior to shipment of the EUT.

RESPONSE: The following statement will be added to our "copyright" page (page 2 of the preliminary draft copy).

Caution: Changes or modifications made in the radio phone, not expressly approved by Motorola, will void the user's authority to operate the equipment.

It does not appear that the Bluetooth schematics were submitted. Please do so.

RESPONSE: Please reference Exhibit 5A submitted on October 21, 2005.