

Polar 5A Internal pictures



CONFIDENTIAL

19 January 2022



Figure 1. Whole device from both sides.




Figure 2. The display module separated.



CONFIDENTIAL

19 January 2022




Figure 3. The connectors have been removed.




Figure 4. The main PWB from component side.




Figure 5. The main PWB from vibra motor side.



CONFIDENTIAL

19 January 2022




Figure 6. Component details 1.




Figure 7. Component details 2.



CONFIDENTIAL

19 January 2022




Figure 8. Battery removed.




Figure 9. OHR PWB visible.




Figure 10. OHR PWB removed.



CONFIDENTIAL

19 January 2022




Figure 11. OHR PWB from component side.




Figure 12. OHR PWB from other side.




Figure 13. OHR PWB component details.

