

Correspondence by Project

Project Number:

1729100161

Correspondence Number	Memo
NUL450191ZWV-1	1) Please indicate the type of modulation employed by the device. A:(Customer Provided) BFSK, +/- 20kHz modulation on carrier 2) For the FCC ID label, please explain whether the label is visible. A: The FCC ID label is located on top the transceiver daughter card. This will be visible during installation and/or while the decorative cover is removed for battery replacement and service. 3) The TCB submittal letter, letter of authority, anti-drug abuse letter and confidentiality request letter all have a different company name listed and a different signer compared to the FCC Grantee database. Please send corrected letters, or as needed, have the company update their Grantee information. A: The TCB Letter, Letter of Authority, Anti-drug abuse letter, and Confidentiality request letter have all been modified and uploaded. 4) The block diagram submitted shows a different type of antenna being used then what is shown in the photos. Please send an updated block diagram. A: The block diagram has been modified and uploaded. 5) The schematics do not match the photos of the device tested, specifically C13 and R19. Also, no schematics were provided for the non-RF boards. A: The schematics have been modified and uploaded and the non-RF board schematics have been uploaded 6) Please provide a correct user manual. The manual provided appears to be for a different device with a different FCC ID. A: The user manual has been modified and uploaded. 7) The TCB contract provided has a company listed other than the Grantee. Please provide a correct TCB contract. A: The TCB contract has been modified and uploaded. 8) The company name and contact do not match the Grantee information on the FCC database. Please correct the application form with the correct information. A: The company name and contact have been modified and submitted.

