



IDX Company, Ltd.

Add: 6-28-11 Shukugawara, Tama-ku, Kawasaki-shi Kanagawa-ken, Japan

Tel: +81-(0)44-850-8831 Fax: +81-(0)44-850-8867

To:

Federal Communications Commission

Authorization & Evaluation Division

7435 Oakland Mills Road

Colombia, Maryland 21046

Declaration

Subject: Project number: R1207114, FCC ID: OFJCW-1-12061202 declaration.

Dear Sir or Madam:

We, IDX Company, Ltd., hereby declare that our product Wireless Video Transmission System, Model Number CW-1.

1. The IR socket is for factory use only. IR port is used for paring of TX and RX and region code setting during the production at factory.
*Refer file: "Region setting instruction"
2. IDX USA sales office, located 19001 Harborage Way, Suite 105 Torrance CA, are now preparing the Sales Agreement between reseller in the United State.
In this Agreement contains following sentences to warn resellers.

"By purchasing and/or reselling IDX 5GHz wireless transmission products with DFS,
"Reseller" agrees to comply with FCC regulations and restrictions.

IDX is required to have all participating resellers sign this agreement which states that the resellers will not import and sell non US authorized IDX 5GHz wireless products with DFS in the United States. The reseller will not tamper with or modify any wireless products from IDX. Resellers that do not sign this agreement will not have authorization from IDX to purchase and/or sell IDX 5GHz wireless products with DFS.

Unauthorized use of restricted frequencies is a violation of law in the United States. Resellers that are found to be in violation of this agreement will be terminated as an IDX reseller for 5GHz wireless products with DFS.

The terms of this agreement will be in effect for one year from the date of signature and will require a renewal signature at the beginning of the second year unless either party is willing to terminate this agreement."

3. The initial EUT test failure was caused by power management. In initial software, product works when there is video transmitting, or the product in semi-sleep mode (lower power), most of functions (includes DFS) do not work. The software upgraded and solved the bug by keep the product power on and DFS works all the time. Products for sales are with new software.

Please contact me if you have any question.

Signature: 和田 康志

Yasushi, Wada

General Manager Software & System

Date: 2012-12-17