



Field Tune-up Procedure

04 December 2005

Attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

RE: Field Tuning Procedures
FCC part 15C: OPA-TB 24-58, and OPA-TB 49
FCC part 90Y: OPA-TB 49

The TB 24-58 and TB 49 radio with the above referenced FCC ID, have no field tunable adjustments. All configuration changes possible are made with either two rotary selector switches and/or via a software serial port as described in the User Manual for this equipment. Therefore there are no separate tuning procedures to submit.

Signatory,

James R. Carlson
CEO and President
Carlson Wireless Technologies Inc.