

## Chris Harvey

---

**From:** Neena Jain [neena.jain@ccsemc.com]  
**Sent:** Monday, September 29, 2008 8:52 PM  
**To:** Chris Harvey  
**Cc:** Thu Chan  
**Subject:** Kyocera 08U11978 OVFKWC-K3802  
**Attachments:** 08U11978-1B FCC PART 22 24 and 27 Report\_Final\_No photos.pdf; 08U11978-1B FCC PART 22 24 and 27 Report\_Final.pdf

Hello Chris,

Please find the engineer's response on the application for this triband phone question asked earlier. Please find the revised report as well.

1. In order to get desired results the engineer Recalibrated, Remeasured and Resetup the AWS band.

rgds,

*Neena Jain*

Account Executive

Compliance Certification Services

47173 Benicia Street, FM, CA 94538

Voice: 510-771-1114

Fax: 510-661-0888

Email: neena.jain@ccsemc.com

<<08U11978-1B FCC PART 22 24 and 27 Report\_Final\_No photos.pdf>> <<08U11978-1B FCC PART 22 24 and 27 Report\_Final.pdf>>