



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

APPENDIX I: INTERNAL EUT PICTURES


PHOTOGRAPH 5: INSIDE COVER





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 6: MAIN PCB IN CHASSIS





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 7: FRONT SHOWING LCD PCB IN CHASSIS





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 8: INSIDE CHASSIS





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 9: LCD PCB FRONT SIDE





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 10: LCD PCB BACK





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 11: MAIN PCB TOP WITH SHIELDS





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


PHOTOGRAPH 12: MAIN PCB TOP WITH SHIELDS REMOVED





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

PHOTOGRAPH 13: MAIN PCB BOTTOM WITH SHIELDS





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

PHOTOGRAPH 14: MAIN PCB BOTTOM SHIELDS REMOVED

