

**Chris Harvey**

**From:** Alice Wong [alice\_wong@hkstc.com]  
**Sent:** Thursday, May 02, 2002 7:46 AM  
**To:** Chris Harvey  
**Cc:** mbosley@metlabs.com; EED - Choy, Kitty  
**Subject:** Re: #12259 Lung Cheong FC ID: P73KGRACER49TX

Dear Chris,

The report have typing error, please see attached file for revised report.  
The Duty cycle is 20 log (0.505) =-5.9dB.

About schematic diagram i have inform the client resubmit the update circuit to us, but now just waiting for customer reply.  
If have any question, please let me know.  
Thanks.

Best Regards  
Alice

----- Original Message -----

From: "Chris Harvey" <CHarvey@metlabs.com>  
To: <alice\_wong@hkstc.com>  
Cc: "Marianne Bosley" <MBosley@metlabs.com>  
Sent: Monday, April 29, 2002 11:16 PM  
Subject: #12259 Lung Cheong FC ID: P73KGRACER49TX

> Alice, below are 2 technical items that need to be corrected for the  
> referenced application:  
>  
> 1) The Schematic Diagram is not correct. Please provide the correct  
> diagram.  
>  
> 2) The Duty Cycle correction factor is stated using 2 different numbers on  
> pages 10 and 17 (of 20). Please verify which number is correct and ensure  
> that the data has been corrected properly.  
>  
> This application will be continued upon receipt of this information.  
>  
> Best regards,  
>  
> Chris Harvey  
>  
> Chris Harvey  
> EMC Lab Director, MET Laboratories, Inc.  
> 1-800-638-6057 x-310  
> charvey@metlabs.com  
>  
> Chris Harvey  
> EMC Lab Director, MET Laboratories, Inc.  
> 1-800-638-6057 x-310  
> charvey@metlabs.com



report-r.PDF

>