



July 15th 2002

To Whom It May Concern:

The following modifications, which were made during testing, shall be implemented in all production bearing **FCC ID: P98-TX902**

Modifications are as follows:

- #1. Add 100 Ohm resistor at the antenna output
- #2. Changed R24 resistor value to 1.5k Ohm
- #3. Changed r26 resistor value to 330 Ohm

Best Regards,

Tony Garcia
President

www.enercise.tv

Enercise, Inc. 3835-R East Thousand Oaks Blvd. #307 Westlake Village, California 91362 866-492-8878 Toll Free 818-540-4273 Tel 818-540-4289 Fax