

TIMCO ENGINEERING INC.
849 NW State Road 45
NEWBERRY, FLORIDA 32669
sid@timcoengr.com
888.472.2424

Mr. Frank Coperich
FCC

SUBJECT: PA8EJ309312ETHC

REFERENCE: TC99825

The pulse train is varied depending on the position of the controls. Attached is a plot of the occupied bandwidth and plots of the worse case pulse train.

Thanks for your help.

Sincerely,

Sid Sanders