Test report no.: 1-2977-21-06/11-A



## Annex A Photographs of the test setup

Photo documentation:

Photo 1: AC conducted



Photo 2: chamber F



2011-05-23 Page 93 of 106


## Test report no.: 1-2977-21-06/11-A



Photo 3: chamber F



Photo 4: chamber C



2011-05-23 Page 94 of 106

## Test report no.: 1-2977-21-06/11-A



Photo 5: chamber C



2011-05-23 Page 95 of 106