Test report no.: 1-2977-56-05/11



Annex A Photographs of the test setup

Photo documentation:

Photo 1: chamber C




Photo 2: chamber C




2011-06-27 Page 133 of 156



Photo 3: chamber C



Photo 4: chamber C



2011-06-27 Page 134 of 156

Test report no.: 1-2977-56-05/11



Photo 5: chamber C



Photo 6: chamber C



2011-06-27 Page 135 of 156



Photo 7: chamber C



Photo 8: AC conducted



2011-06-27 Page 136 of 156

Test report no.: 1-2977-56-05/11



Photo 9: chamber F




Photo 10: chamber F



2011-06-27 Page 137 of 156