



Cisco-Linksys LLC

121 Theory Drive Irvine, CA 92617 (USA)

Phone: 949-261-1288 Fax: 949-823-3002

Date: October 11, 2007

To whom it may concern

It is acknowledged by Cisco-Linksys LLC.. that the modification list below will be installed to our Model: WRVS4400N V1.1 in order to comply with FCC/ IC /CE Approval requirements. These modifications will be incorporated into each unit sold and mass production under the rules.

1. FB30,36--> SBK160808T-600Y-N bead
2. R99.100--> PBY160808T-601y-N bead
3. FB2.3.6.7.8.9.--> PBY201209T-601Y-N bead
4. C130.135.262--> 0 ohm
5. R177.181.183--> 22PF
6. FB15.16.17.33.34.35.--> SBK160808T-600Y-N bead
7. FB17.35--> bypass 5 pf to gnd

Sincerely Yours,

Jennifer Yu / Program Manager

October 11, 2007