

In

Dear Tim:

After we checking your comment, here is our answer.

1. Software difference means different in the content of signal. ID code different in command of the product signal.
2. We have asked our client to retest the duty cycle when the TX signal during "on"., and calculate again.
so we revised the report.
3. The product is working by the piezoelectric device, so it is a mechanical movement, the time of each button push will be different. Your suggest is correct, so we asked our client use the signal with the biggest duty cycle which is control by the ID code to test more. And we use the data to revised the report.

Thank you for your kind assistance.

Best Regards,

Stephanie Hung (ᠰᠡᠫᠤᠨᠭ)

Advance Data Technology Corporation (ᠠᠨᠠᠳᠠᠨᠠᠳᠤᠲᠤᠲᠤᠭᠤᠨ)