

Dear Tim,

Please find the responses as below:

1. The internal photos were updated to mark the antenna location and was uploaded.
2. Updated 731 form was uploaded.
3. Will upload the new block diagram soon. 850 is supported.
4. The testing in 3 axis were investigated, only the worst case position were reported.
5. GPRS can not support voice and as GSM in voice mode, GPRS can not function. Therefore, head SAR only needs to measure GSM, one time slot mode.
6. WLAN can not support VOIP mode and as in GSM mode, WLAN will be disabled.

Thanks a lot.

BR

Daniel