

Hello Tim,

By checking with the manufacturer, the operating frequency should be allocated 2402/2440/2480(MHz) instead of the one tested and reported before (2400/2431/2474(MHz)), please kindly discard the report filed before. we have arranged to re-do all the testes and will be reported and re-uploaded to the ATCB very soon.

The co-submission (FCC ID: TA4PT1FSH31001) is just finished and uploaded. Please kindly review and let us know in case any comments should be arisen.

Thank you!!

Eric 0825