


Test setup photographs for test report 223827A and 223827B



Photograph 1. Spurious radiated emissions test setup



Photograph 2. AC power line conducted emissions test setup

Page 1 (1)