


INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs Worst-Case Radiated Emissions (Front View)




INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs Worst-Case Radiated Emissions

(Back View)



INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs Worst-Case Radiated Emissions

(Front View)




INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs Worst-Case Radiated Emissions

(Back View)




INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs

Worst-Case Radiated Emissions


(Front View)



INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300


Configuration Photographs Worst-Case Radiated Emissions (Back View)



INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs Worst-Case Radiated Emissions (Front View)



INTERTEK TESTING SERVICE

Report No: 16051175HKG-002
#14300

Configuration Photographs Worst-Case Radiated Emissions

(Back View)

