

Correspondence by Project

Project Number:

1274792434

Correspondence Number	Memo
YCU-T50-1	<p>1) Please include additional external photos of the EUT. A photo of the backside of the EUT is missing. Response: The backside photo of the EUT has been added. 2) Please include additional internal photos of the EUT. A photo of the bottom view of PCB 112292 is missing. Response: The bottom view of PCB 11292 has been added. 3) Please provide a corrected operational description. The output power in the operational description is different than what was measured. Response: The operational description has been revised to match up with what was measured. 4) Please clarify the frequency range of the device. The owner's manual and operational description do not match. Response: The operational description has been revised to match up with the owner's manual. 5) Please provide the software manuals OTM02623 and OTM02617 that are used to set the transmitter parameters. Response: The software manual has been uploaded. 6) Does this device allow for output power adjustments? Response: No, the client has stated that there are no user accessible power adjustments 7) Please provide the correct FCC user statement in the owner's manual. Response: The owners manual has been revised to show the correct owner's manual.</p>