

Setting up of the instruments for testing.

1. Figure 1 & 2 is the connecting of the Spectrum Analyser to the TRX.
2. Figure 3&4 is the connecting of the Peak Power Meter to the TRX.



Fig.1.



Fig.2.



Fig.3.



Fig.4.