

TCB Questions and Answers:

TCB question 1:

Please explain how the WLAN feature is disabled. I assume it is through software only (not removal of hardware components) but please confirm it.

Applicant response 1:

The WLAN feature has been disabled by Software. The way this has been done is that the WiFi driver and firmware are not loaded onto X-MET operating system and WiFi chip.

TCB question 2:

Please explain how Oxford Instruments ensures that the host manufacturer (or the user) is unable to re-enable the WLAN feature.

Applicant response 2:

The only way to enable the WiFi is for the main X-MET CPU board to be re-flashed with operating system and software with WiFi support. This is can only be done by an authorised service engineer.