HHP

Upgrade your image.™

www.hhp.com

Corporate Headquarters
Hand Held Products, Inc.
700 Visions Drive
PO Box 208
Skaneateles Falls, NY 13153-0208 USA
+1 800-782-4263
(North America Only)
+1 315-685-8945
Fax: +1 315-685-0049

Subject: Modular Approval Request

FCC ID: HD588352
3/31/04

Dear Application Examiner,

Handheld Products, Inc. d/b/a HHP, TT8870-352 wireless module, FCC ID: HD588352 would like to have your authorization as a modular approval. The requirements of Public Notice DA00-1407 have been met and shown on the following statements.

1. "The modular transmitter must have its own RF shielding." The radio portion of this module has been shielded, please see exhibition External Photo.

2. "The modular transmitter must have buffered modulation/data inputs." The TT8870-352 wireless module contains buffered data inputs; it is integrated in HHP partnumber 80000382-US, PC Card 350. This is the partnumber for Cisco Aironet 350 Series radio with FCC ID: LDK102040.

3. "The modular transmitter must have its own power supply regulation." The TT8870-352 wireless module contains a regulator in the DC input port, in HHP partnumber 80000382-US, PC Card 350. This is the partnumber for Cisco Aironet 350 Series radio with FCC ID: LDK102040.

4. "The modular transmitter must comply with the antenna requirements of section 15.203 and 15.204(C)." The TT8870-352 wireless module meets the FCC antenna requirements. The spurious emission, unique antenna connector and photo of antennas are shown in the application exhibits.

5. "The modular transmitter must be tested in a stand-alone configuration" The TT8870-352 wireless module was tested in a stand-alone configuration via a PCMCIA adapter card. Please see exhibit "Test Setup Photos".

6. "The modular transmitter must be labeled with its own FCC ID number." Please see exhibit "FCC Label" for the FCC ID of this module.

7. "The modular transmitter must comply with any specific rule or operating requirements applicable to the transmitter and the manufacturer must provide adequate instructions along with the module to explain any such requirements." The TT8870-352 wireless module is compliant with all applicable FCC rules. Detail instructions for maintaining compliance are given in the Users Manual.

Page 1 of 2

HHP Charlotte, NC
Phone: +1 800-782-4263
(North America Only)
+1 704-998-3834

HHP Bushnell's Basin, NY
Phone: +1-800-782-4263
(North America Only)
+1 315-685-8945

HHP Europe
Phone: +31 (0) 40 24 24 486

HHP UK
Phone +44 (0) 1925 240055

HHP France
Phone: +33 (0) 1 46 10 41 11

HHP Latin America
Phone: +1 239-263-7600

HHP Brazil
Rio de Janeiro
Phone: +55(21) 2494-7060
Sao Paulo
Phone: +55(11) 5016-3459

HHP Asia
Phone: +85 2 2511 3050

HHP Japan
Phone: +81 3 52127392

![HHP logo](Upgrade your image.™)

www.hhp.com

Corporate Headquarters
Hand Held Products, Inc.
700 Visions Drive
PO Box 208
Skaneateles Falls, NY 13153-0208 USA
+1 800-782-4263
(North America Only)
+1 315-685-8945
Fax: +1 315-685-0049

(continued from page 1)

8. "The modular transmitter must comply with any applicable RF exposure requirements." The EUT is compliant with all applicable RF exposure requirements. RF Exposure is addressed in the exhibit "MPE Data".

Please contact me if you have any further questions.

Thank you for your attention.

Naveen Velagapudi

Naveen Velagapudi
Compliance Engineer
HandHeld Products, Inc. d/b/a HHP
Phone: 315 685 2931
E mail: velagapudin@hhp.com

Page 2 of 2

HHP *Charlotte, NC*
Phone: +1 800-782-4263
(North America Only)
+1 704-998-3834

HHP *Bushnell's Basin, NY*
Phone: +1-800-782-4263
(North America Only)
+1 315-685-8945

HHP *Europe*
Phone: +31 (0) 40 24 24 486

HHP *UK*
Phone +44 (0) 1925 240055

HHP *France*
Phone: +33 (0) 1 46 10 41 11

HHP *Latin America*
Phone: +1 239-263-7600

HHP *Brazil*
Rio de Janeiro
Phone: +55(21) 2494-7060
Sao Paulo
Phone: +55(11) 5016-3459

HHP *Asia*
Phone: +85 2 2511 3050

HHP *Japan*
Phone: +81 3 52127392