OBW NVNT ac80 5290MHz Ant2



OBW NVNT ac80 5530MHz Ant1



OBW NVNT ac80 5530MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5610MHz Ant1



OBW NVNT ac80 5610MHz Ant2



OBW NVNT ac80 5690MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5690MHz Ant2



OBW NVNT ac80 5775MHz Ant1



OBW NVNT ac80 5775MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5180MHz Ant1



OBW NVNT ax20 5180MHz Ant2



OBW NVNT ax20 5200MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5200MHz Ant2



OBW NVNT ax20 5240MHz Ant1



OBW NVNT ax20 5240MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5260MHz Ant1



OBW NVNT ax20 5260MHz Ant2



OBW NVNT ax20 5280MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5280MHz Ant2



OBW NVNT ax20 5320MHz Ant1



OBW NVNT ax20 5320MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5500MHz Ant1



OBW NVNT ax20 5500MHz Ant2



OBW NVNT ax20 5580MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5580MHz Ant2



OBW NVNT ax20 5700MHz Ant1



OBW NVNT ax20 5700MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5720MHz Ant1



OBW NVNT ax20 5720MHz Ant2



OBW NVNT ax20 5745MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5745MHz Ant2



OBW NVNT ax20 5785MHz Ant1



OBW NVNT ax20 5785MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5825MHz Ant1



OBW NVNT ax20 5825MHz Ant2



OBW NVNT ax40 5190MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5190MHz Ant2



OBW NVNT ax40 5230MHz Ant1



OBW NVNT ax40 5230MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5270MHz Ant1



OBW NVNT ax40 5270MHz Ant2



OBW NVNT ax40 5310MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5310MHz Ant2



OBW NVNT ax40 5510MHz Ant1



OBW NVNT ax40 5510MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5550MHz Ant1



OBW NVNT ax40 5550MHz Ant2



OBW NVNT ax40 5670MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5670MHz Ant2



OBW NVNT ax40 5710MHz Ant1



OBW NVNT ax40 5710MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5755MHz Ant1



OBW NVNT ax40 5755MHz Ant2



OBW NVNT ax40 5795MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5795MHz Ant2



OBW NVNT ax80 5210MHz Ant1



OBW NVNT ax80 5210MHz Ant2



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax80 5290MHz Ant1



OBW NVNT ax80 5290MHz Ant2



OBW NVNT ax80 5530MHz Ant1



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.