Tx. Spurious NVNT n40 2422MHz Ant2 Ref

Tx. Spurious NVNT n40 2422MHz Ant2 Emission

Tx. Spurious NVNT n40 2437MHz Ant2 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2437MHz Ant2 Emission

Tx. Spurious NVNT n40 2452MHz Ant2 Ref

Tx. Spurious NVNT n40 2452MHz Ant2 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2412MHz Ant2 Ref

Tx. Spurious NVNT ax20 2412MHz Ant2 Emission

Tx. Spurious NVNT ax20 2437MHz Ant2 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2437MHz Ant2 Emission

Tx. Spurious NVNT ax20 2462MHz Ant2 Ref

Tx. Spurious NVNT ax20 2462MHz Ant2 Emission

END OF REPORT

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.