FAQ

Name of Equipment :
Smart Scaner
Model : IO180-SH
Manufacturer : Infocar Co., Ltd.
FCC ID : 2A66X-IO180-SH
IC : 30192-IO180SH
Connection Type : Bluetooth LE 4.0, Bluetooth
Connectable Terminals :
Android, iOS smartphone(tablet)
Rated Voltage : 12V
Operating Temperature : -20°C ~ 70°C
Weight : 17g
Size : 49x26x23mm
Date of manufacturing : NOV. 2022
Customer Center :
+82-70-7708-6118 / market.infocar@gmail.com
Made in China

FCC COMPLIANCE

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) This device must accept any interference received, including interference that may cause undesired operation.

FCC INTERFERENCE STATEMENT

This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

FCC CAUTION

Any changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate this equipment. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

FCC RADIATION EXPOSURE STATEMENT

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. This equipment should be installed and operated with minimum distance 20 cm between the radiator and your body. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

IC INDUSTRY CANADA STATEMENT

This device complies with Industry Canada licence-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes : (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

IC INDUSTRY CANADA RADIATION EXPOSURE STATEMENT

(Déclaration d'exposition aux radiations)

This equipment complies with IC radiation exposure limits set forth for an uncontrolled environment. This equipment should be installed and operated with minimum distance 20 cm between the radiator & your body.

Cet équipement est conforme aux limites d'exposition aux rayonnements IC établies pour un environnement non con trôlé. Cet équipement doit être installé et utilisé avec un minimum de 20 cm de distance entre la source de rayonnement et votre corps.

01 How to Install

When the car is turned off, attach the terminal to OBD socket shown above, and start the car
(red LED light is up when installed normally).
Fuse box and terminal box should be removed from the cover. If the OBD socket is located on a pedal or other location that you cannot see, please use a flash for installation. Location of OBD socket may vary depending on vehicle's manufacturer and model. Use a PS2 or less than 100 W power

1. Inside the fuse box, the lower left of the driver's seat
2. Under the driver's seat
3. Audio, socket box under the ashtray
   (Renault Samsung, Peugeot)
4. Center console or console box



Infocar

Smart Scanner

CATALOGUE

OBD II
IO180-SH

02 Download

Application Download

Google Play

App Store

Access Google Play Store or App Store
and install 'Infocar'

03 Connection

Bluetooth Setting

Click "Connect" on the top right corner and move to Bluetooth connecting page.

[Android]

Check Bluetooth or Bluetooth LE 4.0 as a connection type and click Infocar180 in the Bluetooth list below. Type “1234” if a PIN number is required.

[iOS]

Check Bluetooth LE 4.0 as a connection type and click Infocar180 in the Bluetooth list below. You have to connect through Bluetooth not from the smartphone setting, but from Infocar application.



Connection may take time depending on the smartphone OS or model.

[AutoRun – Android]

1. Check if you have allowed Infocar to access location.
2. When the engine turns on, Infocar application would be automatically turned on and driving records would be saved.
3. If you can't autorun Infocar, check if the smartphone and vehicle Bluetooth is well connected.
4. Autorun can be delayed depending on smartphone model.

[Connection Failure and How to Solve]

1. Enable smartphone's Bluetooth
2. Deactivate the battery usage optimization.
3. If the problem repeats after you change the setting, reinstall the application and try again.

If the problem persists, please click
"Settings→Ask to Developers" in Infocar app.
Then we will pleasely help you.