

11AX80MIMO_Ant2_6145



11AX80MIMO_Ant1_6385



11AX80MIMO_Ant2_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465



11AX80MIMO_Ant2_6465



11AX80MIMO_Ant1_6545

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6545



11AX80MIMO_Ant1_6625



11AX80MIMO_Ant2_6625

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705



11AX80MIMO_Ant2_6705



11AX80MIMO_Ant1_6785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6785



11AX80MIMO_Ant1_6865



11AX80MIMO_Ant2_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945



11AX80MIMO_Ant2_6945



11AX80MIMO_Ant1_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

12.7. Appendix F: Frequency Stability
Test Result

Frequency Error vs. Voltage									
802.11ax HE20: 6195 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
TN	VL	6195.0097	1.56	6195.0232	3.74	6195.0170	2.74	6195.0105	1.70
TN	VN	6195.0055	0.89	6195.0097	1.56	6195.0208	3.35	6194.9944	-0.91
TN	VH	6194.9943	-0.91	6194.9880	-1.94	6194.9940	-0.97	6195.0159	2.57

Frequency Error vs. Temperature									
802.11ax HE20: 6195 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
70	VN	6194.9824	-2.85	6194.9827	-2.79	6195.0238	3.84	6194.9939	-0.98
60	VN	6194.9957	-0.70	6194.9898	-1.65	6194.9863	-2.22	6194.9766	-3.78
40	VN	6194.9983	-0.27	6194.9786	-3.46	6195.0053	0.85	6194.9814	-3.01
30	VN	6194.9926	-1.20	6195.0146	2.35	6195.0178	2.88	6195.0091	1.47
20	VN	6195.0183	2.95	6195.0212	3.42	6195.0161	2.60	6195.0197	3.19
10	VN	6195.0071	1.15	6195.0009	0.15	6195.0048	0.78	6195.0236	3.82
0	VN	6194.9979	-0.33	6194.9870	-2.10	6195.0015	0.24	6194.9940	-0.97

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Frequency Error vs. Voltage									
802.11ax HE20: 6995 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
TN	VL	6695.0112	1.67	6695.0059	0.88	6694.9984	-0.24	6695.0100	1.49
TN	VN	6695.0189	2.82	6694.9946	-0.80	6695.0036	0.54	6695.0165	2.46
TN	VH	6694.9966	-0.50	6695.0099	1.48	6695.0131	1.95	6695.0249	3.72
Frequency Error vs. Temperature									
802.11ax HE20: 6995 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
70	VN	6694.9924	-1.14	6694.9955	-0.67	6695.0159	2.37	6695.0126	1.88
60	VN	6695.0112	1.68	6694.9768	-3.46	6694.9786	-3.19	6694.9906	-1.41
40	VN	6695.0065	0.96	6694.9855	-2.16	6694.9803	-2.94	6694.9938	-0.93
30	VN	6694.9811	-2.82	6695.0099	1.47	6694.9937	-0.95	6695.0178	2.65
20	VN	6695.0024	0.35	6695.0185	2.77	6694.9830	-2.54	6695.0022	0.33
10	VN	6694.9918	-1.22	6694.9836	-2.46	6695.0023	0.35	6694.9770	-3.44
0	VN	6694.9913	-1.30	6695.0008	0.13	6695.0101	1.51	6694.9886	-1.70

Note: All the mode had been tested, but only the worst data was recorded in the repot.

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

12.8. Appendix G: Contention Based Protocol

Test Mode	Antenna	Channel	Frequency [MHz]	Result [dBm]	Limit[dBm]	Verdict
11AX20MIMO	Ant1	6155	6155	-62.39	-62	PASS
		6455	6455	-62.4996	-62	PASS
		6615	6615	-62.4794	-62	PASS
		7015	7015	-62.2596	-62	PASS
11AX80MIMO	Ant1	6145	6110	-62.4869	-62	PASS
			6145	-62.3684	-62	PASS
			6180	-62.3997	-62	PASS
		6465	6430	-62.2901	-62	PASS
			6465	-62.4776	-62	PASS
			6500	-62.3996	-62	PASS
		6705	6670	-62.2377	-62	PASS
			6705	-62.3314	-62	PASS
			6740	-62.487	-62	PASS
		6945	6910	-62.4779	-62	PASS
			6945	-62.2365	-62	PASS
			6980	-62.4623	-62	PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Test Mode	Antenna	Channel	Interference Frequency [MHz]		Test Time	Is Detected	Verdict
11AX20MIMO	Ant1	6155	Center	6155	1	Yes	PASS
			Center	6155	2	Yes	PASS
			Center	6155	3	Yes	PASS
			Center	6155	4	Yes	PASS
			Center	6155	5	Yes	PASS
			Center	6155	6	Yes	PASS
			Center	6155	7	Yes	PASS
			Center	6155	8	Yes	PASS
			Center	6155	9	Yes	PASS
			Center	6155	10	Yes	PASS
		6455	Center	6455	1	Yes	PASS
			Center	6455	2	Yes	PASS
			Center	6455	3	Yes	PASS
			Center	6455	4	Yes	PASS
			Center	6455	5	Yes	PASS
			Center	6455	6	Yes	PASS
			Center	6455	7	No	FAIL
			Center	6455	8	Yes	PASS
			Center	6455	9	Yes	PASS
			Center	6455	10	Yes	PASS
		6615	Center	6615	1	Yes	PASS
			Center	6615	2	Yes	PASS
			Center	6615	3	Yes	PASS
			Center	6615	4	Yes	PASS
			Center	6615	5	Yes	PASS
			Center	6615	6	Yes	PASS
			Center	6615	7	No	FAIL
			Center	6615	8	Yes	PASS
			Center	6615	9	Yes	PASS
			Center	6615	10	Yes	PASS
		7015	Center	7015	1	Yes	PASS
			Center	7015	2	Yes	PASS
			Center	7015	3	Yes	PASS
			Center	7015	4	Yes	PASS
			Center	7015	5	Yes	PASS
			Center	7015	6	Yes	PASS
			Center	7015	7	Yes	PASS
			Center	7015	8	Yes	PASS
			Center	7015	9	Yes	PASS
			Center	7015	10	Yes	PASS
11AX80MIMO	Ant1	6145	High	6110	1	Yes	PASS
			High	6110	2	Yes	PASS
			High	6110	3	Yes	PASS
			High	6110	4	Yes	PASS
			High	6110	5	Yes	PASS
			High	6110	6	Yes	PASS
			High	6110	7	Yes	PASS
			High	6110	8	Yes	PASS
			High	6110	9	Yes	PASS
			High	6110	10	Yes	PASS
			Center	6145	1	Yes	PASS
			Center	6145	2	Yes	PASS
			Center	6145	3	Yes	PASS
			Center	6145	4	Yes	PASS
			Center	6145	5	Yes	PASS
			Center	6145	6	Yes	PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

			Center	6145	7	Yes	PASS
			Center	6145	8	Yes	PASS
			Center	6145	9	Yes	PASS
			Center	6145	10	Yes	PASS
			Low	6180	1	Yes	PASS
			Low	6180	2	Yes	PASS
			Low	6180	3	Yes	PASS
			Low	6180	4	Yes	PASS
			Low	6180	5	Yes	PASS
			Low	6180	6	Yes	PASS
			Low	6180	7	Yes	PASS
			Low	6180	8	Yes	PASS
			Low	6180	9	Yes	PASS
			Low	6180	10	Yes	PASS
		6465	High	6430	1	Yes	PASS
			High	6430	2	Yes	PASS
			High	6430	3	Yes	PASS
			High	6430	4	Yes	PASS
			High	6430	5	Yes	PASS
			High	6430	6	Yes	PASS
			High	6430	7	Yes	PASS
			High	6430	8	Yes	PASS
			High	6430	9	Yes	PASS
			High	6430	10	Yes	PASS
			Center	6465	1	Yes	PASS
			Center	6465	2	Yes	PASS
			Center	6465	3	Yes	PASS
			Center	6465	4	Yes	PASS
			Center	6465	5	Yes	PASS
			Center	6465	6	Yes	PASS
			Center	6465	7	Yes	PASS
			Center	6465	8	Yes	PASS
			Center	6465	9	Yes	PASS
			Center	6465	10	Yes	PASS
			Low	6500	1	Yes	PASS
			Low	6500	2	Yes	PASS
			Low	6500	3	Yes	PASS
			Low	6500	4	Yes	PASS
			Low	6500	5	Yes	PASS
			Low	6500	6	Yes	PASS
			Low	6500	7	Yes	PASS
			Low	6500	8	Yes	PASS
			Low	6500	9	Yes	PASS
			Low	6500	10	Yes	PASS
		6705	High	6670	1	Yes	PASS
			High	6670	2	Yes	PASS
			High	6670	3	Yes	PASS
			High	6670	4	Yes	PASS
			High	6670	5	Yes	PASS
			High	6670	6	Yes	PASS
			High	6670	7	Yes	PASS
			High	6670	8	Yes	PASS
			High	6670	9	Yes	PASS
			High	6670	10	Yes	PASS
			Center	6705	1	Yes	PASS
			Center	6705	2	Yes	PASS
			Center	6705	3	Yes	PASS
			Center	6705	4	Yes	PASS
			Center	6705	5	Yes	PASS
			Center	6705	6	Yes	PASS
			Center	6705	7	Yes	PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

			Center	6705	8	Yes	PASS
			Center	6705	9	Yes	PASS
			Center	6705	10	Yes	PASS
			Low	6740	1	Yes	PASS
			Low	6740	2	Yes	PASS
			Low	6740	3	Yes	PASS
			Low	6740	4	Yes	PASS
			Low	6740	5	Yes	PASS
			Low	6740	6	Yes	PASS
			Low	6740	7	Yes	PASS
			Low	6740	8	Yes	PASS
			Low	6740	9	Yes	PASS
			Low	6740	10	Yes	PASS
		6945	High	6910	1	Yes	PASS
			High	6910	2	Yes	PASS
			High	6910	3	Yes	PASS
			High	6910	4	Yes	PASS
			High	6910	5	Yes	PASS
			High	6910	6	Yes	PASS
			High	6910	7	Yes	PASS
			High	6910	8	Yes	PASS
			High	6910	9	Yes	PASS
			High	6910	10	Yes	PASS
			Center	6945	1	Yes	PASS
			Center	6945	2	Yes	PASS
			Center	6945	3	Yes	PASS
			Center	6945	4	Yes	PASS
			Center	6945	5	Yes	PASS
			Center	6945	6	Yes	PASS
			Center	6945	7	Yes	PASS
			Center	6945	8	Yes	PASS
			Center	6945	9	Yes	PASS
			Center	6945	10	Yes	PASS
			Low	6980	1	Yes	PASS
			Low	6980	2	Yes	PASS
			Low	6980	3	Yes	PASS
			Low	6980	4	Yes	PASS
			Low	6980	5	Yes	PASS
			Low	6980	6	Yes	PASS
			Low	6980	7	Yes	PASS
			Low	6980	8	Yes	PASS
			Low	6980	9	Yes	PASS
			Low	6980	10	Yes	PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

12.8.1. Test Graphs



11AX20MIMO_Ant1_6155



11AX20MIMO_Ant1_6455



11AX20MIMO_Ant1_6615

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_7015



11AX80MIMO_Ant1_6145



11AX80MIMO_Ant1_6145

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145



11AX80MIMO_Ant1_6465



11AX80MIMO_Ant1_6465

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465



11AX80MIMO_Ant1_6705



11AX80MIMO_Ant1_6705

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705



11AX80MIMO_Ant1_6945



11AX80MIMO_Ant1_6945

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945



11AX20MIMO_Ant1_6155_Center_6155_1



11AX20MIMO_Ant1_6155_Center_6155_2

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6155_Center_6155_3



11AX20MIMO_Ant1_6155_Center_6155_4



11AX20MIMO_Ant1_6155_Center_6155_5

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6155_Center_6155_6



11AX20MIMO_Ant1_6155_Center_6155_7



11AX20MIMO_Ant1_6155_Center_6155_8

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6155_Center_6155_9



11AX20MIMO_Ant1_6155_Center_6155_10



11AX20MIMO_Ant1_6455_Center_6455_1

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6455_Center_6455_2



11AX20MIMO_Ant1_6455_Center_6455_3



11AX20MIMO_Ant1_6455_Center_6455_4

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6455_Center_6455_5



11AX20MIMO_Ant1_6455_Center_6455_6



11AX20MIMO_Ant1_6455_Center_6455_7

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6455_Center_6455_8



11AX20MIMO_Ant1_6455_Center_6455_9



11AX20MIMO_Ant1_6455_Center_6455_10

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_1



11AX20MIMO_Ant1_6615_Center_6615_2



11AX20MIMO_Ant1_6615_Center_6615_3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_4



11AX20MIMO_Ant1_6615_Center_6615_5



11AX20MIMO_Ant1_6615_Center_6615_6

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_7



11AX20MIMO_Ant1_6615_Center_6615_8



11AX20MIMO_Ant1_6615_Center_6615_9

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_10



11AX20MIMO_Ant1_7015_Center_7015_1



11AX20MIMO_Ant1_7015_Center_7015_2

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_7015_Center_7015_3



11AX20MIMO_Ant1_7015_Center_7015_4



11AX20MIMO_Ant1_7015_Center_7015_5

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.