US Tech Test Report: FCC Part 15 Certification
FCC ID: 2AHQD-SENSOR4
Test Report Number: 22-0125
Issue Date: June 6, 2022
Customer: Clean Hands Safe Hands, LLC
Model: Gen4 Sensor

EXTERNAL PHOTOGRAPHS

Figure 1. Top of EUT

US Tech Test Report:	FCC Part 15 Certification
FCC ID:	2AHQD-SENSOR4
Test Report Number:	22-0125
Issue Date:	June 6, 2022
Customer:	Clean Hands Safe Hands, LLC
Model:	Gen4 Sensor

Figure 2. Back of EUT with wall plate

| US Tech Test Report: | FCC Part 15 Certification |
FCC ID:	2AHQD-SENSOR4
Test Report Number:	22-0125
Issue Date:	June 6, 2022
Customer:	Clean Hands Safe Hands, LLC
Model:	Gen4 Sensor

Figure 3. Back of EUT with wall plate removed.

(The EUT is marketed with the wall plate removed.)

US Tech Test Report: FCC Part 15 Certification
FCC ID: 2AHQD-SENSOR4
Test Report Number: 22-0125
Issue Date: June 6, 2022
Customer: Clean Hands Safe Hands, LLC
Model: Gen4 Sensor

Figure 4. Left Side of EUT

US Tech Test Report:	FCC Part 15 Certification
FCC ID:	2AHQD-SENSOR4
Test Report Number:	22-0125
Issue Date:	June 6, 2022
Customer:	Clean Hands Safe Hands, LLC
Model:	Gen4 Sensor

Figure 5. Right Side of EUT

US Tech Test Report: FCC Part 15 Certification
FCC ID: 2AHQD-SENSOR4
Test Report Number: 22-0125
Issue Date: June 6, 2022
Customer: Clean Hands Safe Hands, LLC
Model: Gen4 Sensor

Figure 6. Front of EUT

US Tech Test Report: FCC Part 15 Certification
FCC ID: 2AHQD-SENSOR4
Test Report Number: 22-0125
Issue Date: June 6, 2022
Customer: Clean Hands Safe Hands, LLC
Model: Gen4 Sensor

Figure 7. Bottom of EUT