165.00 mm

15 mm

2.53 mm

145.00 mm

⚠ WARNING

FALL and STRANGULATION HAZARDS:
Infants have suffered head injuries falling from swings and have strangled in straps.
FALL HAZARD: Children have suffered head injuries falling from rockers.

- **ALWAYS** use restraints. Adjust to fit snugly.
- **STOP** using product when infant attempts to climb out (aproximately 9 months).
- Stay near and watch baby during use.This product is not safe for sleep or unsupervised use. If baby falls asleep, remove baby as soon as possible and place baby on a firm, flat sleep surface such as a crib or bassinet.
- **NEVER** lift or carry baby in rocker.
- **STOP** using product when baby starts trying to sit up or has reached [maximum weight not to exceed 20 lbs.], whichever comes first.
- **ALWAYS** place rocker on floor.Never use on any elevated surface.

SUFFOCATION HAZARD: Babies have suffocated when seats tipped over on soft surfaces.

- **NEVER** use on a bed, sofa, cushion, or other soft surface.
- Stay near and watch child duringuse.This product is not safe for unsupervised use or unattended sleep.

This device complies with Part 15 of the FCC Rules.
Operation is subject to the following two conditions:

- this device may not cause harmful interference, and
- this device must accept any interference received, including interference that may cause undesired operation.

Product Name: Auto Baby Swing FCC ID: 2ATQH-BB701 Date of MFR: Sep.2022 Applicable Age: 0-9months
Standard: ASTM F2088-22,ASTM F3084-20,ASTM F963-17 Manufacturer: Foshan Baby Bear Technology Co.,Ltd Tel: 86 0757-27887286
Address: No. 11-3, Xing Ye Zhong Road, Changjiao Residential Committee, Lunjiao, Shunde, Foshan, Guangdong, China. Batch No.: Sep.2022
Importer: ZHU INTERNATIONAL TRADE INC Address: 1441 PASO REAL AVE SPC 202 ROWLAND HGHTS, CA 91748
Customer Service: echoemail83@yahoo.com Tel: 510-316-9610

Label Location: sewing on backside of the seat pad