Appendix A: SAR Setup Photos

Underwriters Laboratories Taiwan Co., Ltd.
This report shall not be reproduced without the written approval of Underwriters Laboratories Taiwan Co., Ltd.

Inner ear



Rear



Underwriters Laboratories Taiwan Co., Ltd.
This report shall not be reproduced without the written approval of Underwriters Laboratories Taiwan Co., Ltd.

Left touch

Underwriters Laboratories Taiwan Co., Ltd.
This report shall not be reproduced without the written approval of Underwriters Laboratories Taiwan Co., Ltd.