11AC20SISO_Ant1_5260

11AC20SISO_Ant1_5280

11AC20SISO_Ant1_5320

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

11AC20SISO_Ant1_5500

11AC20SISO_Ant1_5580

11AC20SISO_Ant1_5700

Eurofins TA Technology (Shanghai) Co., Ltd.   **TA-MB-04-006R**   **Page 38 of 1137**

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

## 11AC20SISO_Ant1_5720

11AC20SISO_Ant1_5745

11AC20SISO_Ant1_5785

11AC20SISO_Ant1_5825

11AC40SISO_Ant1_5190

11AC40SISO_Ant1_5230

Eurofins TA Technology (Shanghai) Co., Ltd.   **TA-MB-04-006R**   **Page 40 of 1137**

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

11AC40SISO_Ant1_5270

11AC40SISO_Ant1_5310

11AC40SISO_Ant1_5510

11AC40SISO_Ant1_5550

11AC40SISO_Ant1_5670

11AC40SISO_Ant1_5710

11AC40SISO_Ant1_5755

11AC40SISO_Ant1_5795

11AC80SISO_Ant1_5210

Eurofins TA Technology (Shanghai) Co., Ltd.   **TA-MB-04-006R**   **Page 43 of 1137**

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

11AC80SISO_Ant1_5290

11AC80SISO_Ant1_5530

11AC80SISO_Ant1_5610

11AC80SISO_Ant1_5690

11AC80SISO_Ant1_5775

11AC160SISO_Ant1_5250

11AC160SISO_Ant1_5570

11AX20SISO_Ant1_5180

11AX20SISO_Ant1_5200

11AX20SISO_Ant1_5240

11AX20SISO_Ant1_5260

| 11AX20SISO_Ant1_5280 |
|---|

11AX20SISO_Ant1_5320

11AX20SISO_Ant1_5500


11AX20SISO_Ant1_5580

11AX20SISO_Ant1_5700

| 11AX20SISO_Ant1_5720 |
|---|

11AX20SISO_Ant1_5745

11AX20SISO_Ant1_5785

11AX20SISO_Ant1_5825

11AX40SISO_Ant1_5190

11AX40SISO_Ant1_5230

11AX40SISO_Ant1_5270

11AX40SISO_Ant1_5310

Eurofins TA Technology (Shanghai) Co., Ltd.　　　**TA-MB-04-006R**　　　　　**Page 51 of 1137**

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

11AX40SISO_Ant1_5510

11AX40SISO_Ant1_5550

11AX40SISO_Ant1_5670

Eurofins TA Technology (Shanghai) Co., Ltd.   **TA-MB-04-006R**   **Page 52 of 1137**

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.

11AX40SISO_Ant1_5710

11AX40SISO_Ant1_5755

11AX40SISO_Ant1_5795

11AX80SISO_Ant1_5210

11AX80SISO_Ant1_5290

11AX80SISO_Ant1_5530

Eurofins TA Technology (Shanghai) Co., Ltd.   **TA-MB-04-006R**   **Page 54 of 1137**

This report shall not be reproduced except in full, without the written approval of Eurofins TA Technology (Shanghai) Co., Ltd.