Tx. Spurious NVNT 1-DH5 2441MHz Ant2 Emission



Tx. Spurious NVNT 1-DH5 2480MHz Ant2 Ref



Tx. Spurious NVNT 1-DH5 2480MHz Ant2 Emission



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT 3-DH5 2402MHz Ant2 Ref



Tx. Spurious NVNT 3-DH5 2402MHz Ant2 Emission



Tx. Spurious NVNT 3-DH5 2441MHz Ant2 Ref



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT 3-DH5 2441MHz Ant2 Emission



Tx. Spurious NVNT 3-DH5 2480MHz Ant2 Ref



Tx. Spurious NVNT 3-DH5 2480MHz Ant2 Emission



END OF REPORT

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.