1TX Antenna 5 MODE – MRU 106+26, Index 82

LOW CHANNEL, 6565 MHz



MID CHANNEL, 6685 MHz



HIGH CHANNEL, 6845 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 106+26, Index 83



LOW CHANNEL, 6565 MHz



MID CHANNEL, 6685 MHz



HIGH CHANNEL, 6845 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 106+26, Index 85



LOW CHANNEL, 6565 MHz



MID CHANNEL, 6685 MHz



HIGH CHANNEL, 6845 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – SU



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]



MID CHANNEL, 6685 MHz [ANT 6]



MID CHANNEL, 6685 MHz [ANT 5]



HIGH CHANNEL, 6845 MHz [ANT 6]



HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 106+26, Index 82



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]



MID CHANNEL, 6685 MHz [ANT 6]



MID CHANNEL, 6685 MHz [ANT 5]

HIGH CHANNEL, 6845 MHz [ANT 6]

HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 106+26, Index 83



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]

MID CHANNEL, 6685 MHz [ANT 6]



MID CHANNEL, 6685 MHz [ANT 5]



HIGH CHANNEL, 6845 MHz [ANT 6]

HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 106+26, Index 85



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]



MID CHANNEL, 6685 MHz [ANT 6]



MID CHANNEL, 6685 MHz [ANT 5]

HIGH CHANNEL, 6845 MHz [ANT 6]



HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – SU



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]



MID CHANNEL, 6685 MHz [ANT 6]



MID CHANNEL, 6685 MHz [ANT 5]



HIGH CHANNEL, 6845 MHz [ANT 6]



HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 106+26, Index 82



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]

MID CHANNEL, 6685 MHz [ANT 6]

MID CHANNEL, 6685 MHz [ANT 5]

HIGH CHANNEL, 6845 MHz [ANT 6]



HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 106+26, Index 83



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]

MID CHANNEL, 6685 MHz [ANT 6]



MID CHANNEL, 6685 MHz [ANT 5]



HIGH CHANNEL, 6845 MHz [ANT 6]



HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE – MRU 106+26, Index 85



LOW CHANNEL, 6565 MHz [ANT 6]



LOW CHANNEL, 6565 MHz [ANT 5]

MID CHANNEL, 6685 MHz [ANT 6]

MID CHANNEL, 6685 MHz [ANT 5]



HIGH CHANNEL, 6845 MHz [ANT 6]

HIGH CHANNEL, 6845 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.4.7. 802.11be EHT80 MODE IN THE UNII-7 BAND

1TX Antenna 6 MODE – SU



LOW CHANNEL, 6625 MHz



MID CHANNEL, 6705 MHz



HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index 91

LOW CHANNEL, 6625 MHz

MID CHANNEL, 6705 MHz

HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index 92

LOW CHANNEL, 6625 MHz



MID CHANNEL, 6705 MHz

HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE – MRU 484+242, Index 93

LOW CHANNEL, 6625 MHz



MID CHANNEL, 6705 MHz



HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – SU



LOW CHANNEL, 6625 MHz



MID CHANNEL, 6705 MHz



HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 91

LOW CHANNEL, 6625 MHz

MID CHANNEL, 6705 MHz



HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 92



LOW CHANNEL, 6625 MHz

MID CHANNEL, 6705 MHz



HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE – MRU 484+242, Index 93



LOW CHANNEL, 6625 MHz



MID CHANNEL, 6705 MHz



HIGH CHANNEL, 6785 MHz

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – SU



LOW CHANNEL, 6625 MHz [ANT 6]



LOW CHANNEL, 6625 MHz [ANT 5]



MID CHANNEL, 6705 MHz [ANT 6]



MID CHANNEL, 6705 MHz [ANT 5]



HIGH CHANNEL, 6785 MHz [ANT 6]



HIGH CHANNEL, 6785 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 484+242, Index 91



LOW CHANNEL, 6625 MHz [ANT 6]

LOW CHANNEL, 6625 MHz [ANT 5]



MID CHANNEL, 6705 MHz [ANT 6]



MID CHANNEL, 6705 MHz [ANT 5]



HIGH CHANNEL, 6785 MHz [ANT 6]



HIGH CHANNEL, 6785 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 CDD MODE – MRU 484+242, Index 92



LOW CHANNEL, 6625 MHz [ANT 6]



LOW CHANNEL, 6625 MHz [ANT 5]



MID CHANNEL, 6705 MHz [ANT 6]



MID CHANNEL, 6705 MHz [ANT 5]



HIGH CHANNEL, 6785 MHz [ANT 6]



HIGH CHANNEL, 6785 MHz [ANT 5]

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL: (510) 319-4000 FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.