LABEL INFORMATION

Equipment:

Invensys iCon Electric Meter
With Utility Meter Transmitter
Model 51ESS

Itron Test Facility
2401 North State Street
Waseca, Minnesota 56093

E0951ESS

Equipment ID Label and Label Placement on the 51ESS Board

Two labels will be placed on the Invensys iCon meter. One label will be placed on the 51ESS board.

9 Point

6 Point

ERE-0162-001 51ESS
FCC ID:E09551ESS
03/04/2002 08

07 12345678

Itron

3 Point

The following label will be placed on the 51ESS board:

Itron logo is 0.19" in height.

Barcode is Code 39. Contains a 2 character ERT Type (07) followed by an 8 character serial number padded with leading zeros. No spaces are in barcode. Barcode is 0.2" in height.

The 9 point serial number contains the 8 character serial number padded with leading zeros.

There should be a minimum of 0.2" of white space on each side of the barcode.

The 3 point date and time is in the format MM/DD/YYYY HH.

Label Material Reference: LBL-0015-001
Ribbon Reference: PNT-0001-001
Label Matrix File Reference: AWL-xxxx-xxx

See picture on next page for details.

Equipment ID Label and Label Placement on the Invensys iCon Meter

The following label will be placed on the meter just underneath the display:

51ESS ERT® INTEGRATED   ERE-0162-001   07 12345678   10/02

The following label will be placed on the bottom side of the meter inside of the clear dome:

FCC ID:E0951ESS
This device complies with Part 15 of the FCC rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) This device must accept any interference received,
including interference that may cause undesired operation.

CONTAINS MERCURY. DON'T PUT IN TRASH.
MANAGE AS HAZARDOUS WASTE.

See picture on next page for details.

FCC ID:E0951ESS
This device complies with Part 15 of the FCC rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) This device must accept any interference received,
including interference that may cause undesired operation.

CONTAINS MERCURY. DON'T PUT IN TRASH.
MANAGE AS HAZARDOUS WASTE.