Report No.: 07176681
Talk Mode

Report No.:07176681
Scan Settings (1 Range)

Frequencies			Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF 60dB

Final Measurement: x QP / + AV
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.		Start	Stop	Name
2	1	9k	30M	EW0700
	12	9k	30M	EW0090



Ctrl No.: N/A

Report No.:07176681

Scan Settings (1 Range)

|--------- Frequencies ----------||---------- Receiver Settings ----------|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Report No.: 07176681
Instant Message
PC's AC Port

Report No.:07176681
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
2	1	9k	30M	EW0700
	12	9k	30M	EW0090



Ctrl No.: N/A

Report No.:07176681

Scan Settings (1 Range)

|--------- Frequencies ----------||---------- Receiver Settings ----------|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV	Delta dB
0.15000	49.1	66.0	-16.9
5.71500	34.3	60.0	-25.7
6.15500	36.6	60.0	-23.4
15.42500	40.5	60.0	-19.5
15.63000	40.5	60.0	-19.5

Frequency MHz	AV Level dBuV	AV Limit dBuV	Delta dB
6.54000	29.4	50.0	-20.6
15.42500	33.8	50.0	-16.2
15.65500	34.0	50.0	-16.0

*** limit exceeded**