CONSTRUCTION PHOTOS OF EUT








BlackBerry Radar R2 IS
PRD-62976-001
FCC ID: L6AITK100-1
IC: 2503A-ITK1001
Input: 3.6 V
Made in: Taiwan
Fabriqué au: Taïwan
ITK100-1
BlackBerry Limited
2200 University Avenue East
Waterloo, ON Canada N2K0A7


2903
II 1 G Ex ia IIC T4 Ga
II 1 D Ex ia IIIC T135°C Da
ETL23ATEX0XXXX
ITS23UKEX0XXXX
Ex ia IIC T4 Ga
Ex ia IIIC T135°C Da
IECEx ETLXX.00XXX
Class I, Division 1, Groups A, B, C, D; T4
Class I, Division 2, Groups A, B, C, D; T4
Class II, Division 1, Groups E, F, G; T4
Class I, Zone 0, AEx ia IIC T4 Ga I Ex ia IIC T4 Ga
Zone 20, AEx ia IIIC T135°C Da I Ex ia IIIC T135°C Da


BlackBerry Radar R2 IS
ITK100-1




winbond
25Q80DVIG
2328
6250
3M100ZX
MEDIATEK
ARM
MT2706W
1907-8MDK
AMWMG2-53
111469
EFR32
FG12P433JG
2335C022VE


1/4 A 125V
IE 458
F2
mmWave antenna
MEDIATEK


winbond


PCB-63783-001


BlackBerry
P/N: BAT-63345-001
S/N: EVE2023120900383



BlackBerry®
Lithium Metal Battery
Non-Rechargeable
BlackBerry Limited | Battery Pack: BAT-63845-001
Subcomponents: (ER34615C+SPC1550A)
WARNING:
Fire, explosion, and severe burn hazard. Do not recharge, disassemble, heat above 212°F (100°C), incinerate, or expose contents to water. Do not crush.
Follow instructions in manual. Consultez le manuel. Siga el manual de instrucciones. Anweisungen in Anleitung beachten.
WARNING / AVERTISSEMENT:
Do not replace battery when an explosive atmosphere is present.
Ne remplacez pas la batterie en présence d'une atmosphère explosive.
P/N:BAT-63845-001
S/N:EVE2023120500388
BlackBerry Limited
Made in China
blackberry.com/recycling
Please dispose of battery according to local laws.