*Block Diagram*

POWER SUPPLY → LC FILTER → RECTIFY → DC/AC TRANSFORM → BURNING THE TUBE