ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901418

Mode: Charging

Tested By:Hong, Report No.:9901418
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	0ms	AUTO	LN OFF	60dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Final Measurement: 0 QP
Meas Time: [illegible]
Subrange: 1k
Ave Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901418
Mode: Charging

Tested By:Hong, Report No.:9901418
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901418
Mode : Standby

Tested By:Hong, Report No.:9901418
Scan Settings :1 Range
Frequencies	Receiver Settings
Start	Stop	Step	IF BW	Detector	M-Time Atten Preamp OpRge
150K	30M	9K	10K	PK	5ms AUTO LN OFF 60dB

Transducer No. Start Stop Name
3 9K 30M EI07E

Final Measurement: 6 dB
Meas Time: 1 sec
Subranges: 16
Acc Margin: -20dB



Ctrl. No.: N/A

Report No.: 9901418
Mode : Standby

Tested By:Hong, Report No.:9901418
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901418
Mode: Transmission

Tested By:Hong, Report No.:9901418
Scan Settings (1 Range)
[------- Frequencies -------] [------- Receiver Settings -------]

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Final Measurement: 2 QP
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Report No.: 9901418
Mode : Transmission

Tested By:Hong, Report No.:9901418
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A