H3D3001　Manual

Product features

Three-button mouse
Optical sensor(800dpi)
USB connection

System requirements:

Windows 98/Me/2000/Xp
USB port

Connecting the mouse

Connect the USB plug to the corresponding USB port of your computer. The plug &
play function of your system will automatically detect that a new device has been
connected.

FCC WARNING

This device complies with Part 15 of the FCC Rules. Operation is subject to the
following two conditions: (1) this device may not cause harmful interference, and (2)
this device must accept any interference received, including interference that may
cause undesired operation.

NOTE: The manufacturer is not responsible for and radio or TV interference caused
by unauthorized modifications to this equipment. Such modifications could void the
user's authority to operate the equipment.