

Tested To Comply
With FCC Standards
FOR HOME OR OFFICE USE
LISTED
I.T.E. ACCESSORY
Mh29992



CAUTION
· Read the product specification before operation.
· Do not disassemble, modify or repair.
· Back up data regularly.
TOSHIBA cannot be held responsible for possible loss of data.
TOSHIBA
DISK DRIVE MK6006GAH
HDD1544 C ZL01 DC 3.3V 500mA
S/N458H0934T 6C2ECA710A0BY002A
E145163
LR39635
N723
H82380060701Q55000026TS
TOSHIBA CORPORATION
MADE IN PHILIPPINES





M1S51264TUH8A0F-37B
512MB-2Rx16
PC2-4200S-444-10-A1
Warranty Void If Removed
0509.EME052280XC.9402286.XX.TW


NANYA 0501
NT5TU32M16AF-37B
TW
59100CPT


N2PC300021
NANYA 0501
NT5TU32M16AF-37B
TW
59100CPT
94V-0
HJ M1


74
75
76
77
78
79
80
81
82
83
84
85
86


ADDA
DC BRUSHLESS
AB0405MB-GC1
DC 5V 0.20A (HIP)
ZP ADDA CORP.
S
CS



H1
CN1
H2
5476282


PCB I/O.H70 CARD READER BOARD.V.A..
15-R01-050011
40-7#36#1.0mm.4L..GREEN
SCN1
1
29
2
30








7421B092 QDBJ ES
INTEL©©'03







intel
EW82801FBM
F5373181
8L7W6
INTEL ©'03
PHILIPPINES


Bluetooth Location
Wireless LAN Location
Antenna for Bluetooth



R-070VA01
A5Y16E-3989
CLAA070VA01
E194548
W
Made in Taiwan
CN1
CN2
MADE IN TAIWAN

CLAA070VA01
R-070VA01
A5Y16E-3989
11BD3UP10B


Antenna for
Wireless LAN